



Water Acceptance Parameters

- 1) Metals (Method 6010B) include: Arsenic, Barium, Cadmium, Chromium, Copper, Lead, Nickel, Selenium, Silver, Zinc, and Molybdenum.
- 2) Mercury (Method 7470A)
- 3) PH (Method 4500H+)
- 4) BOD (Method 5210B)
- 5) VOCs (Method 8260B)
- 6) Total Phosphorus (Method 365.4)
- 7) Ammonia Nitrogen (Method 350.1)